Def		Seemb Ower	55	- 	D :	
Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	(("6616031") or ("5368217") or ("5351872")).PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/08/10 15:31
L2	. 10143	gas near bearing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L3	185	L2 and (gas near bearing) near (rod or shaft or spindle)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L4	30	L3 and tool	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L5	3501	(228/4.1,6.1,6.2,8,9,44.7,47.1,49. 1,49.5).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/08/10 15:36
L6	422	L5 and (die or chip) near (bond or bond\$4 or attach or attach\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L7	109	L6 and bearing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L8	74	L7 and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36

				т		,
L9	9	L8 and (vcm or voice near coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L10	4	L9 and ((load near cell) or (pressure or force or load) near (sense or sensor or detect or detector or measure or measurement or sens\$4 or detect\$4 or measur\$4))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L11	1	L10 and load near cell	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L12	59326	(die or chip) near (bond or bond\$4 or attach or attach\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L13	16	L12 and gas near bearing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L14	4848	L12 and bearing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L15	306	L14 and ((load near cell) or (pressure or force or load) near (sense or sensor or detect or detector or measure or measurement or sens\$4 or detect\$4 or measur\$4))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L16	79	L15 and load near cell	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36

L17	. 58	L16 and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36
L18	3	L17 and (vcm or voice near coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:36

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4678	((228/4.1,6.1,6.2,8,9,44.7,47.1, 49.1,49.5) or (219/56,56.1,56.2, 56.22,56.21)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/08/10 15:40
L2	464	1 and (die or chip) near (bond or bond\$4 or attach or attach\$5)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:40
L3		2 and (gas or fluid) near bearing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:41
L4	1	3 and (vcm or voice near coil)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:41
L5	1	3 and load near cell	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:42
L7	1	4 and 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/08/10 15:42